

BMW X1 xDrive20dA 190 M-Sport

Reference	7619
CC	1995
HP	190
CO ²	134
Body type	SUV/4x4
Status	Status used
1st registration	30/10/2017
Mileage	4900
Fuel	Diesel
Colour	Grey
	Leather Black



Options title

4WD	ABS	Accoudoir central
Airbag driver	Airbag passenger	Airbags side
Alarm	Alloy wheels 19	Appui lombaire ajustable
Automatic climate control	Automatic trunk lid mechanism	Bluetooth
CD	Central locking	Comfort access
Cruise Control	Eclairage ambient	Electric side mirrors
Electric windows	Electrochromic rearview mirror	ESP
Folding rear-view mirrors electrically	Front parking sensor	Head-up display
Heated Seats	Immobiliser	Isofix
Leather pack	Light sensor	MP3
Multifunction steering wheel	Navigation system (GPS)	Panoramic sunroof
Park Assist	Parking camera	Particulate filter
Power steering	Projecteurs LED	Rain sensor
Rear parking sensor	Sound system Harman Kardon	Sport seats
Sunroof	Tire pressure display	Traction control
Trip computer	Tuner DAB	USB input
Vitres arrières surteintées	With service history	