

BMW X1 xDrive20dA 190 M-Sport

Reference	7772
CC	1995
HP	190
CO ²	134
Body type	SUV/4x4
Status	Status used
1st registration	30/10/2017
Mileage	7800
Fuel	Diesel
Colour	Blue
	Alcantara Black



Options title

4WD	Accoudoir central	Alloy wheels 19
Automatic climate control	Automatic trunk lid mechanism	Bluetooth
Central locking	Cruise Control	Electric side mirrors
Electric windows	Electrochromic rearview mirror	ESP
Folding rear-view mirrors electrically	Front parking sensor	Hifi Loudspeaker System
Immobiliser	Isofix	Light sensor
MP3	Multifunction steering wheel	Navigation system (GPS)
Panoramic sunroof	Park Assist	Parking camera
Particulate filter	Power steering	Projecteurs LED
Rain sensor	Rear parking sensor	Sport seats
Sunroof	Tire pressure display	Trip computer
Tuner DAB	USB input	Vitres arrières surteintées