

## BMW X1 xDrive20dA 190 M-Sport

|                  |                 |
|------------------|-----------------|
| Reference        | 7773            |
| CC               | 1995            |
| HP               | 190             |
| CO <sup>2</sup>  | 134             |
| Body type        | SUV/4x4         |
| Status           | Status used     |
| 1st registration | 25/09/2017      |
| Mileage          | 9600            |
| Fuel             | Diesel          |
| Colour           | Black           |
|                  | Alcantara Black |



### Options title

|                                        |                                 |                         |
|----------------------------------------|---------------------------------|-------------------------|
| 4WD                                    | Accoudoir central               | Alloy wheels 18         |
| Automatic climate control              | Automatic trunk lid mechanism   | Bluetooth               |
| Central locking                        | Cruise Control                  | Electric side mirrors   |
| Electric windows                       | Electrochromic rearview mirror  | ESP                     |
| Folding rear-view mirrors electrically | Front parking sensor            | Hifi Loudspeaker System |
| Immobiliser                            | Isofix                          | Light sensor            |
| MP3                                    | Multifunction steering wheel    | Navigation system (GPS) |
| Panoramic sunroof                      | Park Assist                     | Parking camera          |
| Particulate filter                     | Passenger airbag disconnectable | Power steering          |
| Projecteurs LED                        | Rain sensor                     | Rear parking sensor     |
| Sport seats                            | Sunroof                         | Tire pressure display   |
| Trip computer                          | Tuner DAB                       | USB input               |
| Vitres arrières surteintées            | With service history            |                         |