

BMW X1 sDrive18dA 150 Lounge

Reference	7997
CC	1995
HP	150
Body type	SUV/4x4
Status	Status used
1st registration	2/07/2018
Mileage	15700
Fuel	Diesel
Colour	Grey
	Tissue Black



Options title

Accoudoir central	Active pedestrian protection	Alloy wheels 18
Automatic climate control	Automatic trunk lid mechanism	Bluetooth
Central locking	Cruise Control	Electric side mirrors
Electric windows	Electrochromic rearview mirror	ESP
Front parking sensor	Heated Seats	Immobiliser
Isofix	Light sensor	MP3
Multifunction steering wheel	Navigation system (GPS)	Park Assist
Parking camera	Particulate filter	Passenger airbag disconnectable
Power steering	Projecteurs LED	Rain sensor
Rear parking sensor	Tire pressure display	Trip computer
USB input	With service history	